EarlyVoting: October 15 - November 2, 2018
Election Day: November 6, 2018

## ROCKDALE COUNTY BOARD OF ELECTIONS VOTING EQUIPMENT ISSUES

ECTIONS November 6, 2018
General Election

г															_	
	EL	EC1	TION Y	EARLY VOTING (ABSENTEE)												
	Stanton	St. Pius	Lorraine	IN-PERSON											PRECINCT	
	11/6/2018	11/6/2018	11/6/2018	11/1/2018	10/30/2018	10/30/2018	10/28/2018	10/27/2018	10/27/2018	10/26/2018	10/24/2018	10/24/2018	10/24/2019	10/23/2019	10/22/2018	DATE
	8	4	1&2	7	9	<b>_</b>	ပ	18	ω	<b>1</b>	6	9	တ	4	<u> </u>	# TINU
	Unit frozen with voter card still in it, while voter was voting	Outlet section of the unit was smashed and damaged upon delivery to the precinct.	Battery was not charging on Units 1 and 2.	Voter complained that that unit changed vote on unit. Voter did not press Cast Ballot.	Voter complained that the ballot was cast before pressing "Cast Ballot" while reviewing vote at the summary page.	Unit froze while a voter was voting.	Voter complained that the ballot was cast before pressing "Cast Ballot" while reviewing vote at the summary page.	Unit froze while a voter was voting.	Unit froze while a voter was voting.	Voter complained that the ballot was cast before pressing "Cast Ballot" while reviewing vote at the summary page.	Voter complained that that unit changed vote on unit.  Voter did had pressed "Cast Ballot."	Voter complained that the ballot was cast before pressing "Cast Ballot" while reviewing vote at the summary page.	Voter stated that the candidate selected wasn't who she selected. Voter had not pressed Cast Ballot.	Voter complained that the ballot was cast before pressing "Cast Ballot" while reviewing vote at the summary page.	At opening, unit powered down on its own.	ISSUE REPORTED
a PI AINTIFF'S	Moved voter to another unit. Unit was shut down the rest of the day since it was after 5pm.	Replaced the unit.	Checked the battery connections. Placed units on a new power strip & they began charging. Voting resumed on the units.	Precinct Manager cancelled ballot on unit and moved the voter to another unit. Unit 7 was re-calibrated and re-tested before used by the next voter.	Precint Manager tested Voter Access Card in front of voter to show ballot had been cast. Unit 9 was retested before allowing voting to resume on it.	Powered unit off and on and Voter Access Card was ejected. Moved voter to another voting unit and she voted with further delay. Unit 1 was tested before allowing voting to resume on it.	Elections Director tested Voter Access Card in front of voter to show ballot had been cast.	A new Voter Access Card was created for the voter. Powered unit off and on and Voter Access Card was ejected and canceled. Unit 18 was tested before allowing voting to resume on it.	Powered unit off and on and Voter Access Card was ejected. Moved voter to another voting unit. Unit 3 was tested before allowing voting to resume on it.	Elections Director tested Voter Access Card in front of voter to show ballot had been cast. Voter was satisfied.	Voting unit was calibrated and tested.	Precinct Manager cancelled ballot the ballot and moved the voter to another unit without further delay. Unit 9 was recalibrated and re-tested before being allowed to use again.		Elections Director tested Voter Access Card in front of voter to show ballot had been cast. Voter was satisfied.	Unit was not pluged properly. Plugged unit and Voting Resumed.	SOLUTION

